


Optimum Storage Temperature vs Time
for Maximum PS 416



- Temperature to reach maximum Active PS
- Active PS concentration available for pulping

Fig. 5